

Improvements:

1) Pen added to graphs for Ramp Set Point when in Ramp/Soak mode

Bug Fixes:

1) Communication with multiple units when set to RTU causes timeout disconnection

2) Alarm Setup (P3-8) item 11 or 12 - would not allow the user to set both (AL1H and / or AL1L)

3) Not able to change Additional Cycles in the Ramp/Soak Pattern Editor

4) Icon not displayed correctly for Windows 8 and up

5) Program description in Windows Task Manager incorrect

6) Reset to Default button available only when On-Line Configuration is set to Enable