Stride Modbus Gateways firmware revisions

Version 3.5.012 March 11, 2019

1. 1. Fix a TCP re-connect issue characterized by the serial port won't reply "Gateway Target Device Failed to Respond" when Gateway's Ethernet port is down.
2. Disable port22 and 23 by default. If firmware is subsequently downgraded to version 3.5.007 (the only version prior to 3.5.012) the ports will remain disabled by default.
3. Disable NTP
4. General improvements to:
   a. Help file text and help file icon
   b. Device Information, Operating Settings and Serial Settings pages
5. Change Load Factory Default behavior so Reset isn't a separate step
6. Auto refresh Message List screen
7. Add support for the following Modbus function codes under transparent mode:
   0x07
   0x08
   0x16 (22)
   0x17 (23)
   0x0B (11)
   0x0C (12)
   0x11 (17)
   0x14 (20)
   0x15 (21)
   0x18 (24)
   0x2B (43)

8. Add Diagnostics page