
CLICK Programming Software - NewProject1.ckp - [Main Program]
File Edit View Setup Program Instruction PLC Monitor Window Help
Offline
PLC Mode
PLC Error
Nicknames
Address Comments
Rung Comments
Coil Area
Navigation
Program
Function
PLC
CPU Configuration
System Configurati
Com Port1 Setup
Com Port2 Setup
Com Port3 Setup
Scan Time
Watch Dog Timer
Password Setup
Battery Backup Set
I/O Configuration
Interrupt Setup
CPU Built-in I/O S
Software Setup
Software Setup
Manual
Software Manual
Hardware Manual
A
B
C
D
E
AF
THIS INFORMATION PROVIDED BY AUTOMATIONDIRECT.COM TECHNICAL SUPPORT IS PROVIDED "AS IS" WITHOUT A GUARANTEE OF ANY KIND. These documents are provided by our technical support department to assist others. We do not guarantee that the data is suitable for your particular application, nor do we assume any responsibility for them in your application.
1
(NOP)
The Off Delay timer in this rung will delay turning off T1 until 5 seconds after X001 turns off
2
X001
Timer(OFF Delay)
T1
Current Value
Not Retained
Unit
sec
Enable
SetPoint
5
Current
TD1
T1
Output
3
T1
Y001
OUT
4
END
5
(NOP)
6
(NOP)
7
(NOP)
8
(NOP)
9
(NOP)
Instruction List
Instruction
Contact
Contact (NO)
Contact (NC)
Edge Contact
Compare
Coil
Out
Set
Reset
Timer/Counter
Timer
Counter
Advanced
Math
Drum
Shift Register
Copy/Search
Copy
Search
Program Control
Call
For
Next
End
Communication
Receive
Send
F2
F3
^F2
^F3
SH+F2
SH+F3
=
!
>
<
Ready
Bit
Integer
Integer(2 words)
Floating point
Hex
Text
Ascii
Offline
0000/8000
C0-01DR-D
2:1:AF
NUM