Stride SE2 Series managed switches

Firmware revision release notes

Version F0015 – March 2018

1.Update E/IP and Modbus TCP "enable" check box to 3 radio buttons.

2.Modbus TCP update:

    1)Change the port setting Register from "Port Description" to" Port Status"

    2)The Register "Port Description" is set to Read Only

3.Remove HTTPS function

4. Resolve a bug with DHCP option Port Desired IP wrong action when allocating IP addresses.