Stride SE2 Series managed switches

Firmware revision release notes

Version F0016 – November 2021

1. For SE2-SW8M, SE2-SW8M-2C1 and SE2-SW8M-2T1: Resolve a bug with DHCP

option Port Desired IP on port 1

Version F0015 – March 2018

1. Update E/IP and Modbus TCP "enable" check box to 3 radio buttons.

2. Modbus TCP update:

       1)Change the port setting Register from "Port Description" to" Port Status"

       2)The Register "Port Description" is set to Read Only

3. Remove HTTPS function

4. Resolve a bug with DHCP option Port Desired IP wrong action when allocating IP addresses.