


motor protection switch










Connection

Proper operation is subject to three-pole switch load; thus all poles are to be used also when only one-pole or two-pole load is necessary. Connections can be:

Connection diagram





Placing of under-voltage release and shunt release




2 – pole




3 - pole

Placing of auxiliary switch


Assembly





Time-current characteristic

Mean values of operating times for MS 25



Ambient temperature 20°C

Current as a multiplier of the set current